

Geary Public Schools Factual Information

It is not surprising that when considering something as serious as the construction of new school facilities, many have strong opinions. It is our aim in this document to provide factual information to aid you in deciding what you will do on February 12.

1. We've heard it stated that school facilities do not impact student learning. What, though, are the facts?

Facts: The new school will utilize more natural sunlight which can increase student progress 20% faster in math and 26% faster in reading! One consistent research finding across children of all ages is that the temperature in which a person works affects engagement levels and overall productivity—including student achievement.¹ With classrooms in a basement, and consistent HVAC issues, our current facilities make it difficult to meet student needs in this regard. The new school will allow these issues to be addressed in the most cost effective manner possible.


2. We've heard it stated that there isn't a need for a new school at this time. What are the facts?

Facts: The proposed school will be ADA compliant. This is a necessity as we seek to increase the number of stakeholders welcomed into our buildings. In the new facility, no one will be required to use stairs to gain access to classrooms.

Additionally, the issues with our current building are many. Unreliable telecom systems² (located in a janitorial closet), electrical/HVAC/plumbing issues (scorched plugs, locked classroom closet with an exposed sump pump, clogged water lines³), and even structural issues⁴ make it a challenge to deliver daily instruction.

References/Background Information

¹ https://sites.psu.edu/ceepa/2015/06/07/the-importance-of-school-facilities-in-improving-student-outcomes/



Telecom system in the closet.



Telecom system in the closet.

Todd Glasgow Superintendent 110 SW Embree Geary, OK. 73040 405-884-5601 Fax 405-884-2099 tglasgow@geary.k12.ok.us

Bart Daniel, High School Principal 300 S Blaine Geary, OK. 73040 405-884-5605 Fax 405-884-5487 trawls@geary.k12.ok.us



Telecom system in the closet.

Todd Glasgow Superintendent 110 SW Embree Geary, OK. 73040 405-884-5601 Fax 405-884-2099 tglasgow@geary.k12.ok.us Bart Daniel, High School Principal 300 S Blaine Geary, OK. 73040 405-884-5605 Fax 405-884-5487 trawls@geary.k12.ok.us

³ Scorched plug in computer lab

Todd Glasgow Superintendent 110 SW Embree Geary, OK. 73040 405-884-5601 Fax 405-884-2099 tglasgow@geary.k12.ok.us Bart Daniel, High School Principal 300 S Blaine Geary, OK. 73040 405-884-5605 Fax 405-884-5487 trawls@geary.k12.ok.us




³ Sump pump in basement classroom closet

Todd Glasgow Superintendent 110 SW Embree Geary, OK. 73040 405-884-5601 Fax 405-884-2099 tglasgow@geary.k12.ok.us Bart Daniel, High School Principal 300 S Blaine Geary, OK. 73040 405-884-5605 Fax 405-884-5487 trawls@geary.k12.ok.us

³ Sump pump in basement classroom closet

Todd Glasgow Superintendent 110 SW Embree Geary, OK. 73040 405-884-5601 Fax 405-884-2099 tglasgow@geary.k12.ok.us Bart Daniel, High School Principal 300 S Blaine Geary, OK. 73040 405-884-5605 Fax 405-884-5487 trawls@geary.k12.ok.us



³ Corroded water line



³ Corroded water line

Todd Glasgow Superintendent 110 SW Embree Geary, OK. 73040 405-884-5601 Fax 405-884-2099 tglasgow@geary.k12.ok.us Bart Daniel, High School Principal 300 S Blaine Geary, OK. 73040 405-884-5605 Fax 405-884-5487 trawls@geary.k12.ok.us



⁴ Structural issue in basement classroom.

Todd Glasgow Superintendent 110 SW Embree Geary, OK. 73040 405-884-5601 Fax 405-884-2099 tglasgow@geary.k12.ok.us Bart Daniel, High School Principal 300 S Blaine Geary, OK. 73040 405-884-5605 Fax 405-884-5487 trawls@geary.k12.ok.us